

**Metal Bank Superfund Site
Weekly Site Inspection Log
7301 Cottman Avenue
Philadelphia, Pennsylvania**

Date: May 1, 2009 **Name:** Steven Langseder
Weather
Conditions: Drizzle, 60-65°F

General Inspection:

Is the Milnor Street entrance secure?	(Y/N) <u>Yes</u>
Is the Cottman Ave entrance secure?	<u>Yes</u>
Are there any breaches in site security in the site gate/fence?	<u>No</u>

If Yes, describe in detail below and mark on the attached site map.

Site sign remains in good condition?	<u>Yes</u>
If no, please explain:	

Are the circuit breakers locked and secured?	<u>Yes</u>
---	------------

Building 7:

Are the doors to Building 7 locked?	<u>Yes</u>
Has security for Building 7 been breached?	<u>No</u>
Is the high visibility fence and welded wire still in place at the front door?	<u>Yes</u>

Comments:

Exclusion Zone:

Zone remains well defined (i.e., construction fence remains intact)?	<u>Yes/No</u>
Sheet Pile Wall remains in good condition?	<u>Yes</u>
Marine Mattresses remain covered?	<u>No</u>

If no, please specify areas that need to be addressed:

The boundaries of the Exclusion Zone remain defined; however, the high visibility
orange fence will have to be repaired/replaced during re-mobilization to the Site.

Are the fish warning signs still hanging?	<u>Yes</u>
--	------------

Additional Notes or Comments:

Several marine mattress stockpiles were partially uncovered.

**Metal Bank Superfund Site
Weekly Site Inspection Log
7301 Cottman Avenue
Philadelphia, Pennsylvania**

Date: May 1, 2009 **Name:** Steven Langseder

Weather

Conditions: Drizzle, 60-65°F

E&S Measures

Are there any breaches or damage to the silt fence in the Courtyard Area?	(Y/N)
If yes, please describe in detail and mark on attached site map:	<u>No</u>

Are repairs necessary?	<u>No</u>
If yes, please describe in detail and mark on attached site map:	

Are there any breaches in the Support Area?	<u>No</u>
If yes, please describe in detail and mark on attached site map:	

Are repairs necessary?	<u>No</u>
If yes, please describe in detail and mark on attached site map:	

Additional Notes or Comments:

**Metal Bank Superfund Site
Weekly Site Inspection Log
7301 Cottman Avenue
Philadelphia, Pennsylvania**

Date: May 1, 2009 **Name:** Steven Langseder

Weather

Conditions: Drizzle, 60-65°F

E&S Measures

(Y/N)

Are there any breaches in the Exclusion Zone? No

If yes, please describe in detail and mark on attached site map:

Are repairs necessary? No

If yes, please describe in detail and mark on attached site map:

Are there any breaches in the Sheet Pile Wall Area? No

If yes, please describe in detail and mark on attached site map:

Are repairs necessary? No

If yes, please describe in detail and mark on attached site map:

Additional Notes or Comments:

**Metal Bank Superfund Site
Weekly Site Inspection Log
7301 Cottman Avenue
Philadelphia, Pennsylvania**

Date: May 1, 2009 **Name:** Steven Langseder

Weather

Conditions: Drizzle, 60-65°F

Additional Notes:

Bill Burke of TtEC and Steven Langseder of Malcolm Pirnie performed the weekly inspection on Friday, May 1, 2009.

No photographs are included with this report.
